



Communiqué sécurité : Emerillons poignées de commandes DIAMIR SPANTIK

A la suite de la mise en œuvre d'un lot d'émerillons présentant des probables irrégularités de polissage, une usure prématurée de la drisse rouge reliant poignée de commande et émerillon a pu être constatée. (Voir photo)

Il est demandé aux pilotes propriétaires des DIAMIR à partir du N° de série 81 et aux propriétaires de SPANTIK (tous N°) de vérifier régulièrement l'état d'usure de la drisse rouge en question. En cas d'usure anormale, il sera procédé à un échange gratuit de la poignée incriminée.

*safety alert : control handle Swivels for DIAMIR & SPANTIK*

*Following the implementation of a set of swivels with probable polishing irregularities, we observed premature wear of the red connecting halyard between swivel and control. (See photo)*

*The owners/ pilots of DIAMIR from Serial 81 and SPANTIK (all N) are asked to regularly check the wear on the red cord. If abnormal wear appears, there will be a free exchange of the handle.*

